

PS Magazine 2006 Index

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|---|--------------|-------------|
| AIR CONDITIONERS | | |
| ECU louver repair | 640 | 47 |
| FEDCU, space heater, SOUM | 639 | 56 |
| Refrigeration kit tools added | 638 | 60 |
| AIRCRAFT ARMAMENT SUBSYSTEMS | | |
| 7.62mm Mini-gun--Wear gage | 649 | 35 |
| AIRCRAFT AVIONICS | | |
| M130 chaff dispenser--Don't over tighten | 638 | 38 |
| AIRCRAFT LIFE SUPPORT EQUIPMENT | | |
| Air warrior vest--Bandage | 644 | 60 |
| Aircrew survival egress knife | 641 | 39 |
| AIRSAVE body armor | 639 | 35 |
| AIRSAVE--Alternate all-weather fire starter | 638 | 36 |
| AN/PRC-90--Test set info | 640 | 41 |
| Flight suits--Size 52 | 640 | 40 |
| IHADSS--Inspection lenthened | 646 | 39 |
| Survival knives and parts | 640 | 60 |
| Website that lists ALSE equip | 640 | 35 |
| AIRCRAFT, AH-64 | | |
| Avionics bay gaskets | 643 | 39 |
| Gearbox servicing | 641 | 36 |
| IHADDS carry bag use | 639 | 36 |
| M230 gun--Chain replacement | 639 | 26 |
| M260/261 launcher cleaning | 648 | 35 |
| MMA condensation draining | 645 | 35 |
| Primary exhaust cover streamers, don't tie | 640 | 40 |
| R/TRU failure check | 646 | 36 |
| AIRCRAFT, CH-47, CHINOOK | | |
| AN/APX-118--Radar transponder battery | 649 | 39 |
| Closet jam simulation test | 642 | 61 |
| Hydro-mechanical unit vent | 641 | 38 |
| Rescue hatch bolt and nut | 644 | 60 |
| SDC & CDU turn-in critical | 638 | 61 |
| AIRCRAFT, OH-58D, KIOWA | | |
| IFF antenna damage | 642 | 39 |
| MMS--Shroud clamps | 647 | 39 |
| MMS--Thermal imaging sight upgrade | 646 | 38 |
| MMS--Water leaks | 642 | 38 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|---|--------------|-------------|
| AIRCRAFT, UH-60, BLACK HAWK | | |
| AMSS securing suggestion | 642 | 36 |
| AN/APX-118--Radar transponder battery | 649 | 39 |
| APU accumulator handle locked in before use | 644 | 37 |
| APU hydraulic leak checks | 649 | 37 |
| AVA--Nose door modification for hookup | 645 | 36 |
| Blade pin curing time | 649 | 36 |
| Cockpit underseat area not for storage | 646 | 36 |
| EFAB leaks | 643 | 38 |
| HGU-56/P--Proper stowage | 647 | 35 |
| Pitch control rod sealant | 639 | 37 |
| Primary servo seal damage | 646 | 37 |
| Safety wire use restrictions | 639 | 38 |
| Sand removal before washing | 640 | 41 |
| SDC & CDU turn-in critical | 638 | 61 |
| Swashplate linkage check | 648 | 38 |
| Swashplate lubing update | 638 | 61 |
| T700 engines needed | 642 | 61 |
| T700 turbine modules needed | 642 | 61 |
| Tail cone cable, precautions | 638 | 35 |
| Tail wheel lock pin care | 647 | 36 |
| AIRCRAFT, GENERAL | | |
| AN/APR-39 procesor A7 card | 641 | 35 |
| ANVIS maintenance | 649 | 38 |
| ANVIS turned in | 643 | 35 |
| Bird nests | 639 | 39 |
| Corrosion pubs released | 642 | 61 |
| Countermeasures cover--Clean | 638 | 37 |
| Logbooks--Directives changes | 640 | 36 |
| M230--Vibration during flight | 644 | 35 |
| Tire safety cages | 647 | 37 |
| Water removal tools | 644 | 36 |
| Website that lists ALSE equip | 640 | 35 |
| Weight and balance help | 648 | 39 |
| ALARM, CHEMICAL | | |
| ACADA exhaust valve tip | 645 | 23 |
| ACADA--tracking | 649 | 22 |
| ACADA--Turn-in instructions | 641 | 25 |
| ANTENNAS | | |
| AS-3900--Ground strap needed | 641 | 40 |
| OE-254--Turn in unserviceable | 642 | 46 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|---|--------------|-------------|
| AOAP | | |
| Supplies NSNs | 639 | 60 |
| ARMORED COMBAT EARTHMOVER, M9 | | |
| Driver tips | 639 | 16 |
| Engine air vents | 642 | 60 |
| Fan damage | 643 | 19 |
| Operator tips | 646 | 22 |
| ARMORED SECURITY VEHICLE | | |
| Transfer oil level check | 644 | 10 |
| ARMORED SECURITY VEHICLE, M1117 | | |
| Grab handles to be removed | 649 | 61 |
| ARTILLERY EQUIPMENT | | |
| M2 Aiming circle, Unserviceable | 638 | 24 |
| AVLB'S | | |
| Bridge scissoring cable rotation | 639 | 8 |
| PTO shaft doghouse cover | 649 | 9 |
| Recuperator, gear box oil leaks | 640 | 6 |
| BACK COVER | | |
| Check Your Ammo | 645 | 62 |
| Cold-weather Clothing, C-O-L-D | 648 | 62 |
| Don't Let 'Em Bug You | 642 | 62 |
| ESD and Electronic Devices | 644 | 62 |
| Even Tire Cages Age! | 641 | 62 |
| Get the Urge! Urge to Purge! | 646 | 62 |
| Know Hazardous Materials | 640 | 62 |
| PM Isn't Just the Table... | 638 | 62 |
| Scratchy Sez... If it Moves, Communicates | 649 | 62 |
| Take advantage of your armor | 647 | 62 |
| Trust The TM, Not Memory! | 639 | 62 |
| BATTERY, DRY-CELL | | |
| Types of batteries | 645 | 42 |
| BATTERY, LEAD-ACID | | |
| 6TAGM Hawker--Recharge | 645 | 61 |
| Battery care | 644 | 2 |
| Battery terminal covers | 639 | 61 |
| BATTERY, LITHIUM | | |
| BA-5368/U--Testing procedure | 641 | 60 |
| Material safety data sheets | 645 | 45 |
| NSNs, handling, storage | 640 | 42 |
| BATTERY, RECHARGEABLE | | |
| Charger on the move available | 647 | 44 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|--------------------------------------|--------------|-------------|
| Types of batteries | 645 | 42 |
| BODY ARMOR | | |
| Interceptor--Care, cleaning | 646 | 48 |
| Interceptor--Storage | 646 | 52 |
| SAPI--Cleaning, storage | 644 | 50 |
| CABLES | | |
| 26-pair--PM contacts, covers | 643 | 40 |
| Buried cable marking | 643 | 46 |
| CX-13295A/G parts, safety | 643 | 42 |
| Fiber optic cable facts | 639 | 40 |
| CAN, FUEL | | |
| Can differences | 641 | 55 |
| CAN, WATER | | |
| Can differences | 641 | 55 |
| Plastic, parts | 639 | 52 |
| Plastic--Winter care | 638 | 50 |
| CARBINE, M4-SERIES | | |
| Cotton swap problems | 646 | 16 |
| M68 sight installation | 638 | 22 |
| Magazine filler clip | 640 | 17 |
| CARRIER, AMMO, M992 | | |
| Gear selector T-handle | 641 | 9 |
| Shipping container use | 644 | 9 |
| CARRIER, PERSONNEL, M113 FOV | | |
| 200-amp regulator ground strap | 647 | 6 |
| LEDs for dash lights | 644 | 7 |
| M1068--5KW generator cooling | 645 | |
| 8 | | |
| M113A3--No swimming | 649 | 7 |
| M577 Generator--Air shutter settings | 645 | 9 |
| M577-A2/A3--Map Board | 642 | 7 |
| Prop shaft bolts | 639 | 7 |
| Ramp control valve | 644 | 8 |
| Ramp pump, cylinder, wire | 643 | 8 |
| CLOTHING | | |
| ACU contract numbers | 648 | 61 |
| ACU fakes disclosed | 644 | 46 |
| ACU, Non-brightening detergents | 642 | 48 |
| AIRSAVE body armor | 639 | 35 |
| Anticontact gloves | 638 | 51 |
| Army direct ordering program | 647 | 61 |
| Beret fitting | 638 | 52 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|--------------------------------------|--------------|-------------|
| Clean wet weather parka, trousers | 639 | 48 |
| Cleaning cold weather gear | 638 | 46 |
| Cold weather gear | 647 | 51 |
| Cold weather gloves, care | 649 | 48 |
| Desert camo cold weather parka | 647 | 49 |
| Direct Ordering OIF/OEF | 649 | 55 |
| Extreme cold weather socks | 647 | 50 |
| Flight suits--Size 52 | 640 | 40 |
| Gloves for handling hot gear | 641 | 54 |
| Inserts for cold weather mittens | 638 | 60 |
| Sleeping bags--Extra long bivv | 639 | 60 |
| Tech manuals | 648 | 55 |
| Wet weather parka, trousers | 641 | 53 |
| <hr/> | | |
| CLOTHING, PROTECTIVE | | |
| JSLIST--Expiration dates extended | 649 | 61 |
| JSLIST--Hoodstring button | 649 | 23 |
| JSLIST--New storage bag | 649 | 24 |
| JSLIST--Pants measurement | 644 | 19 |
| <hr/> | | |
| COMMERCIAL CONSTRUCTION EQUIP | | |
| Air tank draining | 638 | 21 |
| Painting preparation | 639 | 17 |
| <hr/> | | |
| COMMO ACCESSORIES | | |
| CX-13295A/G parts, safety | 643 | 42 |
| <hr/> | | |
| COMMUNICATIONS EQUIPMENT | | |
| AN/CYZ-10 DTD--lube damage | 647 | 43 |
| AN/GRM-114B--Nine tips | 639 | 43 |
| Bose ITH Headsets--Use, parts | 646 | 44 |
| Commo OFF decal | 642 | 60 |
| ESD guide online | 648 | 61 |
| H-60 handset--Push-to-talk cover | 642 | 61 |
| M-250/350--handset connectors | 641 | 42 |
| MSE RT-1539--Repair address | 641 | 60 |
| MX-306--Canvas carrier | 648 | 43 |
| Signal distribution box parts | 646 | 40 |
| <hr/> | | |
| COMMUNICATIONS SECURITY | | |
| Pubs with security procedures | 641 | 61 |
| <hr/> | | |
| COMPUTERS & SOFTWARE | | |
| Dell battery recall | 641 | 60 |
| Dell laptop battery recall | 644 | 45 |
| GBS TGRS repair part turn in | 638 | 42 |
| IETMs explained, ordering | 649 | 56 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|---------------------------------------|--------------|-------------|
| MSD maintenance | 640 | 52 |
| MSD--Load ETMs, IETMs | 642 | 56 |
| RFID customer support desk | 638 | 60 |
| <hr/> | | |
| CONTAINER HANDLER, RT | | |
| RT 240--Cylinder rod care | 642 | 26 |
| RT-240--Fuel, air system PM | 643 | 20 |
| RTCH--Power cutoff | 647 | 22 |
| <hr/> | | |
| CONTINUITY | | |
| Do TQG PM, But Do It Safely | 641 | 27 |
| Highbrow Hand Tools | 639 | 27 |
| Jack and the PM Beanstalk | 642 | 27 |
| M14 Rifle is Back | 644 | 26 |
| Midshipman Trumpeter | 646 | 27 |
| PM: It's Never Invisible | 640 | 27 |
| PM--A Revolutionary Idea | 643 | 27 |
| RIO LOCO I, A Western Saga | 648 | 27 |
| Rio Loco II, A Western Saga | 649 | 27 |
| Solving a Titanic Mystery | 645 | 27 |
| The Faithful Fusilier | 647 | 27 |
| <hr/> | | |
| CRANES | | |
| ATEC AT 422T--MWO | 649 | 61 |
| LRT-110--Tire NSN | 644 | 55 |
| <hr/> | | |
| DECALS | | |
| Decal markers for vehicle rear | 639 | 12 |
| <hr/> | | |
| DECON | | |
| M100 sorbent decon system | 647 | 54 |
| M12--CD on training, operation | 638 | 54 |
| M12--Fuel tips, hose protection | 642 | 22 |
| M12--Gasoline models turn in | 649 | 60 |
| M17A3--Filter cleaning | 647 | 52 |
| M17--Cuyuna engine parts | 638 | 53 |
| M17-Series---Startup tips | 638 | 54 |
| Sanator, new instructions | 639 | 46 |
| <hr/> | | |
| DEPLOYABLE UNIV CBT EARTHMOVER | | |
| Air systems cleaning | 640 | 24 |
| Blade cutting edge, ripper care | 646 | 24 |
| Coolant tank deterioration | 648 | 25 |
| General PM | 647 | 24 |
| Rough area PM | 638 | 16 |
| <hr/> | | |
| DESERT OPERATIONS | | |
| Solar shades | 643 | 60 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|--------------------------------------|--------------|-------------|
| DRIVER TESTING, TRAINING | | |
| Driver's license forms | 647 | 60 |
| EDITORIAL | | |
| Defending the Constitution... | 646 | 1 |
| Don't Believe Lube Rumors | 648 | 1 |
| Don't Forget Your Equipment | 639 | 1 |
| High Falutin' Commo PM | 643 | 1 |
| PM and the Road Less Traveled | 645 | 1 |
| PMCS With No LO? No Go! | 641 | 1 |
| Save Us From the Truly Frightful! | 638 | 1 |
| The Direction of Good PM | 647 | 1 |
| The Problem with Perfectionism | 642 | 1 |
| The Rest of the Story | 644 | 1 |
| Time Heals All Wounds? | 640 | 1 |
| Urgent for the Important | 649 | 1 |
| ENVIRONMENTAL CONTROL UNITS | | |
| 18K BTU--Modification | 648 | 40 |
| ECU louver repair | 640 | 47 |
| EXCAVATOR, HYEX | | |
| Dipper arm NSN | 644 | 55 |
| FIREFINDER | | |
| Desert lessons learned | 640 | 18 |
| DRUH turnin POC | 647 | 61 |
| General PM | 641 | 16 |
| Publications to aid maintenance | 640 | 21 |
| Seat replaced | 641 | 60 |
| Trailer brake checks | 648 | 18 |
| FORKLIFTS | | |
| ATLAS, VRFL--Steering lubing | 648 | 24 |
| M4K--Hydraulic leaks, no step | 641 | 49 |
| FORMS, GENERAL | | |
| DA Form 2408-4--Online | 648 | 22 |
| FORMS, GENERAL | | |
| DA Form 348, Who keeps? | 638 | 58 |
| Forms--Corrections | 639 | 57 |
| Operator license qualifications | 644 | 56 |
| FORMS, SUPPLY | | |
| Document number source | 646 | 58 |
| FOX NBC VEHICLE | | |
| Tarp, towbar, tool storage, steering | 645 | 22 |
| GENERATOR, SMOKE, M58 | | |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|--|--------------|-------------|
| Grinder spindle bearings | 644 | 60 |
| GENERATORS, GENERAL | | |
| 15-, 30-,60-KW TQG--Voltage regulator kits | 648 | 44 |
| 3-KW TQG Control panel push-pull switch | 647 | 40 |
| 5-KW TQG oil filler cap NSN | 647 | 41 |
| TQG--Choice of batteries | 638 | 45 |
| Wet stacking prevention | 641 | 45 |
| GLOBAL POSITIONING SYSTEM | | |
| DAGR power cable | 645 | 47 |
| DAGR--Battery pack removal | 645 | 46 |
| DAGR--Software check, update | 642 | 47 |
| PLGR, DAGR--Batteries | 648 | 47 |
| PLGR--Memory battery | 638 | 40 |
| Remote antenna and installation kits | 638 | 41 |
| GRADER | | |
| 130G--Fan bearing pulley lubing | 638 | 19 |
| GUN, MACHINE | | |
| 7.62mm Mini-gun--Wear gage | 649 | 35 |
| M197 mount--Attach shield | 640 | 60 |
| M2, M249--Covers | 644 | 16 |
| M2, MK190--Packing for shipping | 645 | 12 |
| M230 gun--Chain replacement | 639 | 26 |
| M230--Vibration during flight | 644 | 35 |
| M240B--Discriminator not needed | 640 | 16 |
| M240--Blank firing adapter | 648 | 61 |
| M240--Mounting ammo can | 644 | 16 |
| M240--Regulator setting for blanks | 641 | 23 |
| M242 gun--CLP for all barrels | 638 | 9 |
| M242 gun--Feeder, select solenoid cover | 638 | 8 |
| M242 Gun--Gyros needed for repair | 644 | 5 |
| M242 gun--Receiver dust clogs works | 648 | 7 |
| M242 gun--Round count, breech replacement | 643 | 7 |
| M242 Gun--Weapon Data Card | 647 | 7 |
| M249, M240B--Barrel marking | 647 | 20 |
| M249, M240B--M145 Reticle light | 644 | 17 |
| M249--AR, LMG differences | 640 | 17 |
| M249--Collapsible buttstock | 649 | 17 |
| M249--Live round check | 642 | 21 |
| M249--Long and short barrels | 647 | 21 |
| M2--Barrel locking grooves | 644 | 14 |
| M2--Buffer body with two slots | 642 | 19 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|---|--------------|-------------|
| M2--Check for defective bolt | 649 | 18 |
| M2--Headspace, timing card | 641 | 60 |
| M2--Safety, M1A2, M1A2 SEP | 647 | 21 |
| M2--Sight mounting info | 646 | 17 |
| M66 ring mount cover | 640 | 13 |
| M66 Ring mount--Won't turn | 642 | 18 |
| M68 reflex sight TM | 640 | 16 |
| MK 19 runaway solution | 643 | 17 |
| MK 19--Adjustable drive lever | 640 | 14 |
| MK 19--Bolt, firing rate | 642 | 20 |
| MK19--Lever adjustment | 647 | 18 |
| Mount information | 639 | 24 |
| Mount NSN changes | 647 | 17 |
| Shield connected to mount | 642 | 16 |
| Weapon mounts shield | 640 | 15 |
| HAZARDOUS MATERIALS AND WASTE | | |
| Drip pans | 640 | 50 |
| Spill kits, drip pillows | 643 | 53 |
| HEATER, PERSONNEL | | |
| FEDCU, space heater, SOUM | 639 | 56 |
| Repair and testing at unit level | 645 | 2 |
| HEATER, SPACE | | |
| Arctic--Operator checklist | 647 | 46 |
| FOSH--Basics | 639 | 53 |
| HELMETS | | |
| ACH fitting | 642 | 52 |
| ACH--Chin strap, screws, tabs | 645 | 49 |
| ACH--Front bracket, class IX | 642 | 60 |
| CVC, PASGT--Paint | 639 | 50 |
| HGU-56/P--Proper stowage | 647 | 35 |
| HGU-56/P--Zetaliner not approved | 642 | 35 |
| Night vision device mounts | 647 | 45 |
| HI MOBILITY ARTILLERY ROCKET SYS | | |
| MSU not a coatrack | 638 | 13 |
| HI MOBILITY ENGINEER EXCAVATOR | | |
| Air filter, dust bowl, cab air system | 641 | 46 |
| Bucket PM | 646 | 21 |
| Cold weather tips | 638 | 18 |
| Fuel tank vent cleaning | 641 | 48 |
| Hydraulic hose recoil spring spool | 640 | 22 |
| Mirror, air dryer, fenders | 639 | 14 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|-------------------------------------|--------------|-------------|
| Spare tire stowage, bucket drain | 639 | 15 |
| Wheel lug nuts | 643 | 22 |
| <hr/> | | |
| HOWITZER, GENERAL | | |
| HTU system setup | 640 | 9 |
| <hr/> | | |
| HOWITZER, SP, M109A6 PALADIN | | |
| Elevation cylinder leak evaluation | 642 | 9 |
| Gear selector T-handle | 641 | 9 |
| Hatch stop pin lubing | 647 | 9 |
| Segment board cleaning | 648 | 9 |
| Shipping container use | 644 | 9 |
| <hr/> | | |
| INTERNET | | |
| DSP specs, standards online | 642 | 50 |
| LOGNet--Tactical SOPs available | 643 | 56 |
| Logons and Passwords | 644 | 58 |
| Motor Pool website URL updated | 640 | 60 |
| SB 38-101 migrated to WebLIDB | 638 | 56 |
| Telemaintenance help & training | 645 | 54 |
| <hr/> | | |
| KITCHEN EQUIPMENT | | |
| MBU--Flame sensor replacement | 644 | 48 |
| MBU--Fuel cap gasket | 645 | 48 |
| MBU--MWO fuel delivery block | 643 | 50 |
| RESET program | 649 | 52 |
| <hr/> | | |
| LASER OBSERVATION SET | | |
| AN/PVS-6--Battery, BB-326/U | 645 | 47 |
| <hr/> | | |
| LAUNDRY UNIT, M85 | | |
| Flame detector replaced | 649 | 54 |
| <hr/> | | |
| LOADER, SCOOP-TYPE | | |
| MW24C--Alternator | 644 | 55 |
| MW24C--Oil filter | 644 | 55 |
| <hr/> | | |
| LOGISTICS EXCELLENCE AWARDS | | |
| 2006 DOD winners | 646 | 61 |
| Second annual CLEA winners | 645 | 58 |
| <hr/> | | |
| LOGISTICS MANAGEMENT | | |
| DA Form 348, Who keeps? | 638 | 58 |
| DISCOM/COSCOM replaced | 647 | 58 |
| DRRS-A replaces USR | 648 | 56 |
| FED LOG screens updated | 646 | 57 |
| RFID tags, guides, batteries | 639 | 58 |
| WebLIDB/ILAP merge to LIW | 640 | 58 |
| <hr/> | | |
| MAINTENANCE MANAGEMENT | | |
| Driver's badge requirements | 642 | 59 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|--------------------------------------|--------------|-------------|
| Driver's license forms | 647 | 60 |
| Forms--Corrections | 639 | 57 |
| Operator license qualifications | 644 | 56 |
| Property book, AR 710-2 updated | 639 | 61 |
| SB 38-101 migrated to WebLIDB | 638 | 56 |
| Services parts kits | 648 | 58 |
| Telemaintenance help & training | 645 | 54 |
| <hr/> | | |
| MAINTENANCE, GENERAL | | |
| MWO Regulation updated | 643 | 60 |
| <hr/> | | |
| MASK, PROTECTIVE | | |
| M40, M42--Mildew checks | 644 | 18 |
| M40/M42, M45, M48--Bad canisters | 648 | 48 |
| M40/M42, M45--MWOs | 643 | 24 |
| M40/M42--Do not fold for storage | 646 | 55 |
| M40/M42--Turn in excess | 641 | 61 |
| M45--Drink tube blockage | 643 | 23 |
| PATS--Instructional DVD | 641 | 61 |
| Turn in old masks | 641 | 24 |
| <hr/> | | |
| MEDICAL EQUIPMENT | | |
| Tool kit info from manufacturer | 638 | 61 |
| <hr/> | | |
| MILES | | |
| M1 tank firing circuit protection | 643 | 5 |
| <hr/> | | |
| MISSILE, AVENGER | | |
| Headspace and timing cable | 638 | 13 |
| M3P MG--remove mount | 638 | 12 |
| Slew-to-cue secondary, ARIL | 644 | 61 |
| Slew-to-cue test procedure | 648 | 20 |
| <hr/> | | |
| MISSILE, HELLFIRE | | |
| Launcher electronics repair | 641 | 61 |
| Launcher shipping boxes, storage | 642 | 14 |
| <hr/> | | |
| MISSILE, ITAS | | |
| M1134 AGTM--ITAS | 642 | 3 |
| MITAS--Starting procedure, lock care | 642 | 15 |
| <hr/> | | |
| MISSILE, JAVELIN | | |
| Use right shipping container | 643 | 61 |
| Use shipping containers | 645 | 10 |
| <hr/> | | |
| MISSILE, PATRIOT | | |
| Access door closings | 649 | 20 |
| AKO website on repairs | 647 | 16 |
| <hr/> | | |
| MISSILES, GENERAL | | |
| M260/261 launcher cleaning | 648 | 35 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|-------------------------------------|--------------|-------------|
| MLRS | | |
| Boom PM | 639 | 18 |
| Breather Valve Blowby | 647 | 8 |
| Coolant filler neck bolts | 645 | 7 |
| Fuel shutoff lever use | 645 | 6 |
| Generator, regulator NSNs | 639 | 6 |
| MSU not a coatrack | 638 | 13 |
| Paralleling alternators, recycling | 646 | 18 |
| W75, W76 cables | 646 | 20 |
| MORTARS | | |
| 120-mm--MWO for firing pin | 649 | 61 |
| Headsets, improved grease, nut | 648 | 21 |
| M1129E1 mortar BII | 643 | 2 |
| NBC EQUIPMENT | | |
| CBRN web site for info | 643 | 26 |
| Computer spread sheet, track info | 644 | 20 |
| Hotline name change | 640 | 61 |
| Training films | 644 | 20 |
| Training help, website | 641 | 26 |
| NIGHT VISION EQUIPMENT | | |
| AN/PVS-14 eyecup adapter rings | 641 | 44 |
| ANVIS maintenance | 649 | 38 |
| Night vision device mounts | 647 | 45 |
| O-rings prevent moisture damage | 644 | 44 |
| Unserviceable parts needed | 648 | 42 |
| PACKAGING | | |
| Heat-treated lumber for crating | 645 | 50 |
| PERSONAL EQUIPMENT | | |
| Duffel bag buckles | 641 | 60 |
| Gloves for handling hot gear | 641 | 54 |
| Lightsticks--Battery powered | 640 | 48 |
| Molle, shoulder, chest straps | 639 | 61 |
| Sleeping bags--Zipper care | 638 | 48 |
| PISTOLS | | |
| Holsters, waist, thigh, shoulder | 646 | 15 |
| M9 Magazines--Jamming | 641 | 22 |
| M9--Locking block | 649 | 60 |
| M9--Magazine coating message | 638 | 25 |
| M9--New locking block needs plunger | 643 | 17 |
| M9--White dots on sights | 649 | 19 |
| PS MAGAZINE | | |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|---------------------------------------|--------------|-------------|
| PS website | 649 | 60 |
| PUBLICATIONS | | |
| Financial Liability guide | 649 | 60 |
| MSD--Load ETMs, IETMs | 642 | 56 |
| MWO Regulation updated | 643 | 60 |
| Property book, AR 710-2 updated | 639 | 61 |
| Pubs accounts, ordering pubs | 641 | 56 |
| Unit equipment publication lists | 649 | 59 |
| PUMPS | | |
| 350 GPM Water--Engine air cleaner kit | 645 | 21 |
| 350-GPM Fuel Pump Gauges | 644 | 54 |
| 350-GPM Fuel--Pump NSN | 644 | 54 |
| RADIAC EQUIPMENT | | |
| AN/VDR-2--Strap NSN | 649 | 25 |
| RADIO SET, SINCGARS | | |
| Antenna mounts--HMMWV reinforcement | 645 | 38 |
| General PM for older models | 642 | 42 |
| HMMWV radio rack mounting riv-nuts | 647 | 42 |
| Internet controller testing | 648 | 45 |
| RADIO SETS, GENERAL | | |
| AN/PRC-148(V) radio used with ITH | 638 | 44 |
| RADIO TERMINAL SETS | | |
| Air and gas particle filter NSNs | 638 | 43 |
| RFID | | |
| RFID customer support desk | 638 | 60 |
| RIFLE, M14/M21 | | |
| AN/PVS-10 night sight mounting | 643 | 18 |
| Anti-reflection device NSN | 644 | 61 |
| M14 Rifle is Back | 644 | 26 |
| Magazines and scopes | 646 | 15 |
| RIFLE, M16-SERIES | | |
| Bandolier uses | 644 | 15 |
| Cotton swap problems | 646 | 16 |
| Dry firing vs clearing | 643 | 14 |
| M68 sight installation | 638 | 22 |
| Magazine filler clip | 640 | 17 |
| RIFLE, SNIPER | | |
| M24--Repair turn-in procedure | 643 | 16 |
| XM107 Conversion to M107 | 641 | 20 |
| ROLLER | | |
| CS-563D--Final drive NSN | 644 | 55 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|--|--------------|-------------|
| Propulsion control valve and shift lever | 646 | 25 |
| RS28 Tampo--Gear shifting | 646 | 23 |
| RS28 Tampo--Headlight NSN | 644 | 55 |
| RS28 Tampo--Throttle, F/R cables | 644 | 55 |
| SAFETY | | |
| Safety board components | 644 | 40 |
| SATELLITE COMMUNICATION | | |
| AN/TSR-8 tripod nut damage | 648 | 46 |
| Waveguide radiation leak check | 642 | 40 |
| SENTINEL RADAR SYSTEM | | |
| Diagnostic equipment checks | 649 | 21 |
| Radar control terminal, cable PM | 645 | 24 |
| SHELTERS | | |
| Commo--Heat, humidity, sand & dust control | 649 | 41 |
| Lighting lamp, ballast, starter | 642 | 60 |
| Roof damage costly | 649 | 45 |
| Solar shades | 643 | 60 |
| SHOP EQUIPMENT | | |
| Tire cage NSNs | 649 | 10 |
| SHOTGUN | | |
| Mossberg--Front swivel stud NSN | 642 | 60 |
| SMALL ARMS | | |
| Blank firing adapters identified | 638 | 23 |
| Cleaning once is enough | 645 | 11 |
| Corrosion from humidity in arms room | 645 | 14 |
| DA Form 2408-4--Online | 648 | 22 |
| Dry firing vs clearing | 643 | 14 |
| Dummy ammo NSNs | 641 | 21 |
| Gauging--Clean first | 638 | 26 |
| M68 reflex sight knobs | 643 | 18 |
| On-site repair team | 643 | 12 |
| SARET--Team cost being paid | 644 | 61 |
| Shield connected to mount | 642 | 16 |
| Spacesaver universal rack system | 639 | 20 |
| SMALL EMPLACEMENT EXCAVATOR | | |
| Backhoe control handle knob | 644 | 54 |
| BII Tools | 644 | 54 |
| Cab raising procedure | 646 | 26 |
| Engine oil filter | 646 | 26 |
| Fire extinguisher | 644 | 54 |
| Shock mount bolts | 638 | 61 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|---|--------------|-------------|
| Shutdown procedure | 638 | 20 |
| Tool box latch | 644 | 54 |
| <hr/> | | |
| SMART | | |
| Rejections have value | 643 | 58 |
| Spin-on fuel filter--SMART idea | 645 | 18 |
| <hr/> | | |
| STORAGE | | |
| Storage bin ordering | 642 | 49 |
| <hr/> | | |
| STRYKER ICV | | |
| Air filter cleaning | 640 | 2 |
| Bilge water disposal | 647 | 2 |
| Driver vision enhancer cable supports | 645 | 3 |
| Hatch latches--Cleaning and lubing | 643 | 3 |
| Hydraulic fluid levels | 641 | 3 |
| Lubing, gunner's panel and machine gun | 638 | 3 |
| M1129 mortar wiper seal band clamp | 638 | 2 |
| M1129E1 mortar BII | 643 | 2 |
| M1133 MEV--Drivers seatback lowering | 649 | 2 |
| M1134 AGTM--ITAS | 642 | 3 |
| MITAS--Starting procedure, lock care | 642 | 15 |
| NBC heater plugs | 647 | 3 |
| Ramp cam locks | 644 | 6 |
| Slat armor latches | 639 | 2 |
| Towing--Transfer disengaged | 640 | 5 |
| Transfer shifting caution | 646 | 6 |
| Troop hatch opening | 639 | 3 |
| Vent fan airflow | 642 | 2 |
| Weapons station sight care | 648 | 2 |
| Winch precautions | 641 | 2 |
| <hr/> | | |
| SUPPLY, GENERAL | | |
| Army direct ordering program | 647 | 61 |
| Document number source | 646 | 58 |
| FED LOG screens updated | 646 | 57 |
| Fringe parts defined | 644 | 57 |
| Ice scraper | 638 | 60 |
| Parts bags | 639 | 61 |
| Penetrating oil | 643 | 5 |
| Repairable turn-in--complete assemblies | 649 | 14 |
| RFI replace, regular supply | 645 | 57 |
| Rubber tiedown straps | 642 | 60 |
| Sidewalk salt | 638 | 60 |

TANK, M1-SERIES

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|---------------------------------------|--------------|-------------|
| Annual service kit components | 645 | 61 |
| Battery care | 644 | 2 |
| Bore evacuator gasket | 640 | 61 |
| Bore evacuator service | 642 | 5 |
| Breech handle becomes COEI | 645 | 5 |
| Breechblock plunger tool modification | 641 | 6 |
| Cannon tube cleaning | 639 | 4 |
| Cleaning, high pressure, steam | 642 | 6 |
| Damage from high pressure water | 641 | 4 |
| Drivers alert panel differences | 638 | 7 |
| Engine cumbuster liner turn-in | 645 | 4 |
| Fuel cap filter cartridges | 649 | 3 |
| Gun mount exerciser mounting | 648 | 3 |
| Gun tube disposal instructions | 644 | 60 |
| Gun tube replacement warning | 642 | 4 |
| Gun tube, clean bore evacuator | 639 | 5 |
| Gunner's primary sight installation | 648 | 4 |
| Gunner's sight coverup | 648 | 5 |
| HALON extinguisher replaced | 647 | 61 |
| Hand-held fire extinguisher | 649 | 4 |
| LRUs--Replace seals | 643 | 5 |
| M1A1 AIM--Stabilization test | 640 | 61 |
| M1A2 SEP--GPS ELRF bracket | 649 | 5 |
| Newsletters on the web | 640 | 61 |
| PEO website | 644 | 61 |
| Recuperator, gear box oil leaks | 640 | 6 |
| Shock absorber sight glass | 640 | 7 |
| Smoke generator | 643 | 4 |
| Supplemental parts lists | 642 | 6 |
| Torque wrench for gun tube | 638 | 6 |
| Track skirt falling | 646 | 7 |
| Turret safety screens | 638 | 5 |
| Website for troubleshooting | 638 | 4 |
| <hr/> | | |
| TENTS | | |
| DRASH, POCs, NSNs | 648 | 50 |
| GP Medium--Tent poles | 648 | 54 |
| Poles, lines and pins | 644 | 60 |
| Rules for tent living | 641 | 50 |
| Solar systems--Tent pins | 643 | 60 |
| <hr/> | | |
| TEST EQUIPMENT | | |
| AN/GRM-114B--Nine tips | 639 | 43 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|--------------------------------------|--------------|-------------|
| DSESTS web site | 640 | 61 |
| STE-M1/FVS repair | 644 | 5 |
| Website for troubleshooting | 638 | 4 |
| TIRES | | |
| Tire chains, use | 648 | 10 |
| Tire/wheel assembly repairs | 646 | 10 |
| Wheel lift | 639 | 10 |
| TOOLS | | |
| Bolt extraction kit | 649 | 26 |
| Component list upgrades | 639 | 61 |
| GMTK--Wheels for toolbox | 644 | 53 |
| Grease adapter kit parts | 647 | 57 |
| Hand impact wrench components | 644 | 22 |
| Portable electric impact wrench | 647 | 56 |
| Refrigeration kit tools added | 638 | 60 |
| SECM--Wrong socket set | 642 | 24 |
| STE-M1/FVS repair | 644 | 5 |
| Welding outfit using batteries | 642 | 25 |
| TRACTOR, D7E/F/G | | |
| Fuel tank level line needed | 648 | 26 |
| Transmission shifting | 647 | 26 |
| TRAILERS | | |
| PLS trailer--Safety chain latch | 648 | 17 |
| TRAILERS, SEMI | | |
| Chock blocks--order or make | 643 | 11 |
| M1000--Lug nuts | 644 | 10 |
| M172A1--Landing leg NSNs | 648 | 16 |
| M871A2--Air brake chamber | 644 | 11 |
| M871-Series--Safety ladder | 648 | 16 |
| Purpleheart or Apitong wood | 640 | 10 |
| TRAINING | | |
| Foreign language training | 643 | 60 |
| Online driver's training | 646 | 60 |
| Ordnance Maint Management University | 641 | 59 |
| Safety training online | 643 | 61 |
| TRUCK, 1 1/4-TON, HMMWV | | |
| 3-point seat belt assembly | 642 | 13 |
| 4L80E transmission troubleshooting | 641 | 10 |
| 6.5-l Engine injector timing changed | 645 | 61 |
| Add-on armor TB | 640 | 12 |
| Air cleaner, hood NO STEP | 647 | 13 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|--|--------------|-------------|
| Air filter pre-cleaner | 648 | 13 |
| Alternator and parts kits | 640 | 11 |
| Alternator ear spacer needed | 645 | 17 |
| Ballistic glass damage from UV | 639 | 60 |
| Blackout light | 639 | 60 |
| Brake pads may be defective | 645 | 16 |
| Coolant ratio | 645 | 61 |
| Door latch striker needed | 649 | 10 |
| Gunner shield parts | 644 | 12 |
| Gunner station mockup | 645 | 15 |
| HMMWV radio rack mounting riv-nuts | 647 | 42 |
| M1114--Cooper seat dangerous | 642 | 61 |
| M1114--SMART card | 647 | 61 |
| M1114--Turret handle NSN | 643 | 60 |
| M1151--Spring breaking | 647 | 61 |
| M997/A1--AC compressor belt | 649 | 60 |
| New starter not repairable | 643 | 61 |
| Oil pressure changes | 646 | 61 |
| Seatbelt extended | 647 | 14 |
| Serpentine belts | 639 | 60 |
| Snow plow kit | 639 | 13 |
| Spare tire carrier | 640 | 60 |
| Steering shaft locknuts, torque | 646 | 10 |
| Steering shaft lube needed | 649 | 11 |
| Swamper tires not to be used | 638 | 61 |
| Tire chains improved | 646 | 61 |
| Tire pressure for up-armored | 643 | 61 |
| Tire studs/nuts, looseness | 641 | 13 |
| Tires---Super swamper no go | 648 | 12 |
| Tow bars--Uapproved | 649 | 61 |
| Underbelly armor PMCS | 644 | 13 |
| Up-armored tire pressure | 646 | 13 |
| Weapon mounts shield | 640 | 15 |
| <hr/> | | |
| TRUCK, 2 1/2-TON | | |
| M35-series pressure for 11.00R20 tires | 648 | 16 |
| M44-series parking brake check | 642 | 11 |
| M44-series slave starting, turn off switch | 641 | 15 |
| <hr/> | | |
| TRUCK, 5-TON, M939-SERIES | | |
| ABS light explained | 642 | 10 |
| ABS troubleshooting | 646 | 14 |
| Air brake line draining | 649 | 16 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|--|--------------|-------------|
| Armored truck Smart card | 647 | 10 |
| Cab Cracks Make M939 NMC | 646 | 61 |
| <hr/> | | |
| TRUCK, FMTV | | |
| Add-on Armor cautions | 638 | 14 |
| Air/hydraulic unit gasket leak | 640 | 13 |
| Cat engine warranty | 643 | 61 |
| Door hinge bolts | 648 | 14 |
| M66 ring mount cover | 640 | 13 |
| M66 Ring mount--Won't turn | 642 | 18 |
| Tire chains and speeds | 646 | 61 |
| <hr/> | | |
| TRUCK, HEMTT | | |
| Air box drain kit | 644 | 60 |
| Crane turntable lubing | 648 | 15 |
| Engine and container NSN | 640 | 60 |
| Filters, valve exercise, HAV | 649 | 12 |
| Fuel-water separator damaged | 643 | 10 |
| M978--Hose reel gasket | 645 | 20 |
| M978--Purging solution | 640 | 60 |
| Slave receptacle cap | 645 | 20 |
| Spin-on fuel filter--SMART idea | 645 | 18 |
| Tire chains required on rear wheels | 648 | 16 |
| Transmission dipstick tube NSN | 640 | 60 |
| <hr/> | | |
| TRUCK, M1070 HET | | |
| Air compressor oil return line | 641 | 14 |
| Secondary fuel filter replacement | 645 | 20 |
| Transmission hose rubbing | 642 | 12 |
| <hr/> | | |
| TRUCK, M915-SERIES | | |
| Coolant filter kit | 639 | 60 |
| Intervehicular receptacle power | 647 | 15 |
| M915A3---Lug nut | 645 | 20 |
| M915A4--A/C drive belt | 645 | 20 |
| M915A4--Trans ECU 65-mph upgrade | 641 | 60 |
| Tachometer kit | 645 | 20 |
| Wiper motor, valve replacement | 645 | 19 |
| <hr/> | | |
| TRUCK, PALLETIZED LOADING | | |
| CTIS hose assembly | 648 | 17 |
| Fuel system electric priming pump filter | 643 | 12 |
| PLS trailer--Safety chain latch | 648 | 17 |
| Secondary fuel filter replacement | 645 | 20 |
| <hr/> | | |
| TRUCKS, GENERAL | | |
| Cab insulation adhesive | 648 | 17 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|---|--------------|-------------|
| Repairable turn-in--complete assemblies | 649 | 14 |
| Steering wheel security chain | 639 | 11 |
| Tire cage NSNs | 649 | 10 |
| Tire chains, use | 648 | 10 |
| Tire/wheel assembly repairs | 646 | 10 |
| Wheel lift | 639 | 10 |
| <hr/> | | |
| VEHICLE, FIGHTING, M2/M3 BRADLEY | | |
| -A3/M7A3 BFIST--Distribution box breaker | 641 | 7 |
| -A3--Turret training | 644 | 4 |
| Armor damage means NMC | 640 | 8 |
| Fuel pump matched to engine | 643 | 6 |
| Fuel shutoff lever use | 645 | 6 |
| Generator, regulator NSNs | 639 | 6 |
| M242 gun--CLP for all barrels | 638 | 9 |
| M242 gun--Feeder, select solenoid cover | 638 | 8 |
| M242 Gun--Gyros needed for repair | 644 | 5 |
| M242 gun--Receiver dust clogs works | 648 | 7 |
| M242 gun--Round count, breech replacement | 643 | 7 |
| M242 Gun--Weapon Data Card | 647 | 7 |
| Newsletters on the web | 640 | 61 |
| PEO website | 644 | 61 |
| Personnel heaters--Year-round checks | 646 | 8 |
| PLGR cable damage | 648 | 61 |
| Roadwheel lubrication, clean sight glass | 649 | 6 |
| TOW ballistic sight door stops | 648 | 6 |
| <hr/> | | |
| VEHICLE, RECOVERY, M88A1 | | |
| Driver periscope brow pads | 642 | 7 |
| Personnel door hinge lube | 638 | 10 |
| Seat replaced with two-piece assembly | 642 | 8 |
| Transmission oil | 641 | 8 |
| <hr/> | | |
| VEHICLE, RECOVERY, M88A2 | | |
| Engine oil fill tube damage | 648 | 8 |
| Oil drain plug installation | 649 | 8 |
| Voltage regulator circuit breaker | 638 | 10 |
| <hr/> | | |
| VEHICLES, COMBAT | | |
| Air filter freezing | 639 | 9 |
| Combat vehicle evaluation team info | 643 | 60 |
| Lubrication | 647 | 4 |
| <hr/> | | |
| VEHICLES, GENERAL | | |
| Battery terminal covers | 639 | 61 |
| Combat identification panels | 646 | 2 |

| <i>Subject</i> | <i>Issue</i> | <i>Page</i> |
|--------------------------------|--------------|-------------|
| Commo OFF decal | 642 | 60 |
| Decal markers for vehicle rear | 639 | 12 |
| Drip pans | 640 | 50 |
| Hand impact wrench components | 644 | 22 |
| Ice scraper | 638 | 60 |
| Penetrating oil | 643 | 5 |
| Rubber tiedown straps | 642 | 60 |
| Services parts kits | 648 | 58 |
| Thermal identification panels | 646 | 12 |
| <hr/> | | |
| WELDING | | |
| Welding outfit using batteries | 642 | 25 |